Leak Investigation Form & Meter Maintenance Request Form

Arrival Date & Time	
01/11/2017 11:08	
Method	CGI Test
Flame Pack	CGI %
PPM	Lel
Leakator 10 % Scale	201
Initial Detection	Confirmed
•	
Location	Cover
Pressure	€ Class
▼	
GUC Meter Condition	Customer Piping/Appliance Condition
☐ Left On	□ Turned Valve Off At
☐ Left Off	Appliance
□ Locked Out	□ Tagged Customer's Leak
■ Meter Seal Installed	□ Relit Pilots
□ Leak Repaired	Equipment Isolation Tag Number
Gas Off Time	
mm/dd/yyyy:	
Completed Date & Time	
mm/dd/yyyy:	
Remarks	

Leak Investigation Form & Meter Maintenance Request Form

Asset ID:	@ map help
MMR1489	Map Satellite
Account:	
GUC GAS	
Asset Class:	
Meter Maintenance Request	
Asset Description:	
Meter Maintenance Request	2
Date Installed:	
01/25/2017	A
Parent Asset Key:	+
	Google
Asset Tag:	Map data @2017 Terms of Use Report a map error You may drag the marker or select one of these methods:
	Locate Find Address Enter Coordinates
■ Read QR Using Webcam	Enter Cooldinates
Attributes	(35.610042, -77.390964) 903 Bancroft Ave, Greenville, NC 27834, USA
	OJA .
COMPLETED:	
MAINTENANCE COMPLETED	GPS Timed out
no values defined	•
DUE:	
NCOMPLETE.	
INCOMPLETE:	
Meter Status:	
A Maria Garbaria anno ind	
⚠ Meter Status is required Comments:	
comments.	
* required	
▲ Comments is required	
Photo:	
Choose File No file chosen	
Corrosion Area:	
Other (Describe):	
≡ Stakeholder	
Add Additional Stakeholders	