

GREENVILLE UTILITIES COMMISSION

QUESTIONS AND ANSWERS FOR 22-68

RFB FOR INSTALLATION OF MT. PLEASANT TO SUGG 115KV TRANSMISSION LINE

12/1/2022 at 4:00PM

1. The RFP calls for installing double circuit 795 from structure 1 to 8 and the distribution framing for structures 1 through 7 reflect that however structure 8 distribution framing only shows one distribution circuit framed as tangent to continue and no framing to dead-end the second 795 circuit which stops at structure 8. Is the drawing wrong or the reference wrong or do we need a new drawing?

The drawing is incorrect. The drawing is missing a deadend crossarm between the top tangent arm and the bottom deadend arm. An updated drawing will be provided when available.