GREENVILLE UTILITIES COMMISSION QUESTIONS AND ANSWERS FOR 25-58 RFB FOR HIGH-SPEED TURBO BLOWER 10/2/2025 @ 2:00 PM

- 1. Please confirm if blower airflow and total system airflow for DP1 shall be corrected to 11,000 SCFM?

 Yes configure blower system to deliver 11,000 SCFM.
- 2. It is understood that the existing NX500D blower at site is equipped with louvered inlet. Please confirm if one (1) 30" inlet expansion joint shall be removed from the scope of the new NX500D blower?

Yes – delete the intake expansion joint as we will be using the louvered intake.